

# QUESTIONS & ANSWERS

Kill your exam at first Attempt



**IBM**

## P6040-025

*IBM SurePOS 700 Series Models 743 and 784 Technical Mastery*

<https://killexams.com/pass4sure/exam-detail/P6040-025>



**Answer:** B, D, F

**QUESTION:** 60

A customer wants to perform inventory management, software distribution, and event notification remotely for their SurePOS x43 and x84 systems. Which product supports these three functions on all SurePOS x43 and x84 supported operating systems?

- A. Wired for Management (WfM)
- B. Remote Management Agent (RMA)
- C. System Management BIOS (SMBIOS)
- D. Remote Deployment Manager (RDM)

**Answer:** B

**QUESTION:** 61

On which model is an 80GB hard disk drive and a CD/DVD standard?

- A. S83
- B. C83
- C. S43
- D. C43

**Answer:** D

**QUESTION:** 62

Which port is located on the front of the 743 system?

- A. RS-232
- B. PC USB
- C. Powered USB
- D. Audio mic-in/line-out

**Answer:** C

**QUESTION:** 63

Which statement is true about TechLine?

- A. TechLine is a telephone service where users record their questions and receive answers via email.
- B. TechLine is an Internet service where users type in their questions and receive the answers via email.
- C. TechLine is an Internet service that enables users to access IBM technical archives for answers to their questions.
- D. TechLine is a telephone service that reaches level-two support personnel who can immediately answer users' questions.

**Answer:** B

**QUESTION:** 64

With which model does the DVD burner drive come standard?

- A. model 784
- B. model C43
- C. model C84
- D. model 743

**Answer:** C

**QUESTION:** 65

Which three types of ports are standard on all SurePOS x43 and x84 models? (Choose three.)

- A. two VGA ports
- B. two PC USB ports
- C. two RS-485 ports
- D. one parallel port
- E. two powered USB ports
- F. audio mic-in/line out ports

**Answer:** A, B, F

**QUESTION:** 66

What are two precautionary steps that must be taken before beginning any SurePOS 700 removal or replacement procedure? (Choose two.)

- A. update the system BIOS to the latest level
- B. disconnect the power cord from the external power source
- C. follow standard electrostatic discharge prevention methods
- D. run diagnostics using the IBM Diagnostics for POS Systems and Peripherals tool

**Answer:** B, C

For More exams visit <https://killexams.com/vendors-exam-list>



*Kill your exam at First Attempt....Guaranteed!*